

# HIGH VOLTAGE MAST



## ASSEMBLY INSTRUCTIONS



ENERGYENCYCLOPEDIA.COM


# INFO

**PARTS MARKED WITH A GLUE ICON AND/OR A GREEN ARROW NEED TO BE GLUED TOGETHER**






ENERGYENCYCLOPEDIA.COM






ENERGYENCYCLOPEDIA.COM







ENERGYENCYCLOPEDIA.COM





ENERGYENCYCLOPEDIA.COM





09 6x